AD NUMBER AD877332 LIMITATION CHANGES TO: Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;
Administrative/Operational Use; 10 MAY 1970.
Other requests shall be referred to Assistant Chief of Staff for Force Development,
Washington, DC 20310.

AUTHORITY

AGO ltr 29 Apr 1980



DEPARTMENT OF THE ARMY OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310

Wef. Doc. the

27 November 1970

(23 Nov 70) AGDA (M)

FOR OT UT 702297

~

~

SUBJECT: Operational Report - Lessons Learned, Headquarters, 36th

Signal Battalion, Period Ending 30 April 1970

N BEN Y REFER TO

SEE DISTRIBUTION

1. Subject report is forwarded for review and evaluation in accordance with paragraph 4b, AR 525-15. Information of actions initiated as a result of subject report should be forwarded to ACSFOR OT UT within 90 days of receipt of covering letter.

2. Information contained in this report is provided to insure appropriate benefits in the future from lessons learned during current operations and may be adapted for use in developing training material.

BY ORDER OF THE SECRETARY OF THE ARMY:

1 Incl ...

VERNE L. BOWERS Major General, USA Acting The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Armor School

US Army Field Artillery School

US Army Infantry School

US Army Signal School

US Army Southeastern School

Copies furnished:

Office, Chief of Staff, US Army


Deputy Chiefs of Staff

LE But Joct to special export controls and secul

ASSISTANT CHIEF OF STAFF FOR FORCE DEVELOPMENT (ARMY) ATTN: FOR OT UT, WASHINGTON, D.C. 20310

Total document to prior governovel of Tracadittal vith prior grand of and made only vith prior

DISTRIBUTION (Cont'd)
Chief of Research and Development
Assistant Chiefs of Staff
Chief of Engineers J.
Commanding General, Deseret Test Center
Commandant of the Marine Corps
Defense Documentation Center
USAF Project RAND
Commanding Officers
US Army Limited War Laboratory
US Army Logistics, Doctrine Systems & Readiness Agency
US Army Mobility Equipment Research & Development Center



DEPARTMENT OF THE ARMY HEADQUARTERS, 36TH SIGNAL BATTALION (CA) APO San Francisco '96491

1 OMAY 1970

SCCPV-SG-CA-O

SUBJECT: Operational Report - Lessons Learned, 36th Signal Battalion (CA), Period Ending 30 April 1970, ROS GSFOR-65 (R2)

SEE DISTRIBUTION

1. Operations: Significant Activities

- a. During the past reporting period the operational activities of the 36th Signal Battalion have been geared to a program of communications phase down. ARVNIZATION plans were also drafted for various sites throughout the Battalion area of operation.
- (1) Nui Ti: The relay site at Hill 837 was relocated on the ARVN site at Nui Ti. The relocation was done to afford vehicular access to the site for resupply and maintenance pickup.
- (2) Lai Khe: The 1st Infantry Division redeployed to CONUS thoreby eliminating the need for dial telephone service. The AN/TCC-28 at Lai Khe was relocated to Di An. It is presently being maintained but is not in operation. The disposition of the AN/TCC-28 is pending instructions from higher headquarters.
- (3) Bien Hon: The Flame switchboard and the BTAC switchboard were consolidated and rodesignated Flame switch. The consolidation resulted in greatly improved telephone service for the MACV/CORDS subscribers of III CTZ and also reduced dwplication of equipment.
- (4) Bien Hoa: The AN/MSQ-73 was replaced by two (2) SB-675 patch panels. This move reduced numerous circuit outages due to problems encountered in the frame of the AN/MSQ-73 van. Control of circuits through the SB-675's is simplier and more in line with MOS skills authorized by our TO&E.
- (5) Bicn Hoa: The outside plant was rehabilitated to meet the Air Force standards of cable installation. The project is completed and is presently awaiting final inspection by Air Force GEEIA Team subsequent to turn over to the Air Force.
- (6) Lai Khe: The outside plant is ready for turn ever to ARVN. It was rehabilitated and necessary transfer documents were prepared, however, signatures have not been acquired due to the location of the frame. MACV

FOR OT UT 702297 Inclosure

requires the frame to be relocated outside of the MACV Compound instead of in its present location to allow ARVN access without entering the MACV Compound.

2. <u>Lessons Learned</u>: Commander's Observations, Evaluations and Recommendations:

- a. Personnel: None
- b. Intelligence: None
- c. Operations:
- (1) Cutover of AN/TRC-111 systems.
- (a) OBSERVATION: Since the beginning of the reporting period the 36th Signal Battalion has turned over much of its system responsibility to the 327th Signal Company, 39th Signal Battalion, who are installing AN/TRC-Ill equipment to replace the AN/GRC-50 equipment presently in operation. With this cutover of communications to the AN/TRC-Ill the 36th Signal Battalion has deactivated 14 systems leaving the Battalion with 21 systems in operation. Three more systems will be deactivated in the first few days of the new reporting period, leaving 18 systems in operation.
- (b) EVALUATION: The new high capacity AN/TRC-III equipment has proved quite good in its capability for 96 channel operation over 1 system as compared to 4 systems needed for the same capacity of AN/CRC-50 systems.
- (c) LESSONS LEARNED: When communications is being cutover from AN/GRC-50 to AN/TRC-Ill systems experience has proved that both ends must have identical circuit engineering orders to eliminate errors in circuit placement causing extensive trouble-shooting which extends circuit outage time.

(2) Utilization of the AN/TRC-111 Cable

- (a) OBSERVATION: In the cutover of circuits from the AN/GRC-50 to the AN/TRC-111, new cable was required for termination of the new system at the TRC-111 and for gaining access to the patch panel and frames. Some of the required cable was installed before new bunkers and pads were in the correct or final locations.
- (b) EVALUATION: Proper planning and coordination is necessary in any project to eliminate unnecessary loss of man-hours and waste of material and equipment. Some of the cable was installed prior to the installation of the TRC-lll equipment and thus was cut, shorted or damaged due to traffic and the emplacement of equipment. In other cases equipment was relocated from original plans and cables were not long enough to reach the equipment.
- (c) RECOMMENDATION: That all equipment be in place or at least the ex ct location known by cable teams and installers prior to the installation of cable and that adequate coordination and planning be made to eliminate unnecessary retermination of interconnecting cables.

(3) Installation of Test Shots

- (a) OBSERVATION: Prior to the relocation of the relay site from Hill 837 to Nui Ti, test shots were established between Nui Ti and Bien Hoa, and Nui Ti and Han Tan. The length of the shot exceeded the range of the equipment and the system did not profile. Nevertheless the result of testing revealed the systems to be adequate.
- (b) EVALUATION: It is essential that all precautions be observed when test shots are made to insure that all data is correct, antennas are at proper heights, and that all equipment to be used on the system is tested.
- (c) RECOMMENDATION: All equipment should be thoroughly tested by personnel involved in installation and supervision of test stations or systems so that all shortcomings are discovered prior to its actual use.
 - d. Organization: None
 - e. Training:
 - (1) Incdequately Trained Operators.
- (a) OBSERVATIONS: Newly assigned 31M personnel directly out of the MOS school in most cases are not adequately trained in the proper procedures for drop and insert operation with AN/GRC-50 PCM systems.
- (b) EVALUATION: Extensive on the site training of new personnel proves to be a continued requirement for this type operation.
- (c) RECOMMENDATION: That MOS producing schools teach or expand the training for operators to include drop and insert operation with AN/GRC-50 PCM equipment.

f. Logistics:

- (1) Inadequate Supply Support.
- (a) OBSERVATION: Although the situation has improved during the quarter, the line units continue to encounter difficulty in obtaining certain items through supply channels.
- (b) EVALUATION: The supply system is not adequately meeting demands of units. There is a critical shortage of trained and experienced supply personnel. lst Logistical Command's policy on follow-up prevents adequate control of recuisitions by the using unit.
- (c) RECOMMENDATIONS: More over-all command emphasis be given at all echolons to insure adequate stockage at DSU's and that depot continue to tighten controls, to insure priority system is not being improperly utilized. Increase input of personnel into supply MOS' at DA level since critical shortage appears to be Army-wide. Increase number of PLL

school allocations (one week course given in Vietnam). Reverse or modify lst Logistical Command's "no follow-up" policy to be more realistic with units mission requirements.

g. Communications: None

h. Material: None

1. Other: None

1 Incl Organization Chart C. E. MCKWIGHT JR.

LTC, SigC

Commanding

Distribution:
2-CINCUSARPAC, ATTN: GROP-DT, APO 96558
1-CG, USASTRATCOM-PAC, Schofield Barracks, Hawaii, APO 96577
3-CG, USARV, ATTN: AVHGC-DST, APO 96375
1-CG, 1st Signal Brigade (USASTRATCOM), ATTN: SCCPV-OP-AD, APO 96384
16-CO, 2d Signal Group, APO 96491

21: MAY 1970.

SCCPV-30-00 (10 May 70) 1st Ind

SUBJECT: Operational Report - Lessons Leswood, 26th Signal Datislion (CA), Period Ending 30 April 1970, RUB CCFCR-65 (R2)

DA, Has, 2d Signal Group, AFC OF 96491

TO: Commanding Ceneral, 1st Signal Brigade, ATTM: 0001 V-OF, WO IT 90004

- 1. Subject report is forwarded in accordance with list Signal Brigade Supplement 1 to AN 505-15.
- 2. The report has been reviewed and concurred to by this healquarters.

DUNATO CERNOS

Commanding

NOT REPRODUCIBLE

SCCPV-OP-ACN (21 May 70) 2nd Ind SUBJECT: Uperational Report-Lessons Learned, 36th Signal Battalion (CA), Period Ending 30 April 1970, RGS CSFOR-65 (R2)

DA, HQ, 1st Signal Brigade (USASTRATCOM), APO 96384 17 June 1970

TO: Commanding General, United States Army, Vietnam, ATTN: AVHGC-DST, APO 96375

- 1. Subject report is forwarded in accordance with AR 525-15.
- 2. This headquarters has reviewed the report and concurs in it.

FOR THE COMMANDER.

J. M. Beyersdorf CAT

Major, AGC
Adjutant Com

CF:

Commanding General, U.S. Army Strategic Communications Command, ATTN: SCC-OPS-RT, Ft Huachuca, Arisona 85613 Commanding Officer, 2d Signal Group, APO 96491 Commanding Officer, 36th Signal Battalion, APO 96491

AVHGC-DST (10 May 70) 3d Ind SUBJECT: Operational Report - Lessons Learned, 36th Signal Battalion (CA) Period Ending 30 April 1970, RCS CSFOR-65 (R2)

Headquarters, United States Army Vietnam, APO San Francisco 96375 1 7 JUL 1970

THRU: Commanding General, United States Army Strategic Communication Command-Pacific, ATU 96557

TO: Commander in Chief, United States Army Pacific, ATTN: GPOP-DT, APO 96558

1. This Headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 30 April 1970 from Headquarters, 36th Signal Battalion (CA) and concurs with comments of indorsing headquarters.

2. Comments follow:

a. Reference item concerning "Inadequate Supply Support," page 3, paragraph 2f(1): concur. This Headquarters has established the following standards to be attained by each supply and maintenance DSU; Demand satisfaction (percent fill of requests which match the DSU stockage list) equal to 70% and demand accommodation (percent of requests which match the DSU stockage list) equal to 85%. DSU's failing to achieve the above goals will receive assistance from subordinate commands and this Headquarters so that the described standards may be attained. Utilization of the priority system is being monitored by this Headquarters. This Headquarters is cognizant of the problems in this area and has instituted measures, to include command review of all high priority requests, to eliminate abuse of the priority system. The "no follow-up" policy is presently being reviewed. It is tentatively planned for the follow-up policy to be reinstituted by the end of the 1s+ Quarter FY 71. No action by USARPAC or DA is recommended.

b. Reference item concerning "Inadequately Trained Operators," page 3, paragraph 2e(1): concur. In addition, the PCM(MEDCAP) operators course, taught at the Southeast Asia Signal School #1 should be considered as a means of teaching in-country personnel who are not adequately MOS qualified. Action by USARPAC is recommended.

FOR THE COMMANDER:

CPT, AGC

Assistant Adjutant General

Cy furn: 1st Sig Bde 36th Sig Bn SCCP-OP3 (10 May 70) 4th Ind SURJECT: Operational Report - Lessons Learned, 36th Signal Battalion (CA), Period Ending 30 April 1970, RCS CSFOR - 65 (R2)

Headquarters, U. S. Army Strategic Communications Command-Pacific, APO San Francisco 96557 0 1 AUG 1970

TO: Commander in Chief, U. S. Army, Pacific, ATTN: GPOP-DT, APO 96558

- 1. Subject report is forwarded in accordance with AR 525-15.
- 2. This headquarters has reviewed subject report and offers the following comments:
- a. Reference paragraph 2c(1), page 3: Insufficient evidence of a deficiency is presented upon which to base either a concurrence or a nonconcurrence. The fact that MOS 31M personnel require OJT to become skilled in their duties is not unique. This is the responsibility of the unit commander. Should there be a deficiency in the CONARC school base for MOS 31M, adequate evidence must be presented upon which to base a POI change.
 - b. Concur with the remainder of the report as indorsed.

FOR THE COMMANDER:

A. J. SHORT MAJ, AGC Adjutant General

CF:

CG, USARV, APO 96375 wo incl

CG, 1st Sig Bde (USASTRATCOM), APO 96384 wo incl

CO, 2d Sig Gp (USASTRATCOM), APO 96491 wo incl

CO, 36th Sig Bn (USASTRATCOM), APO 96375 wo incl

GPOP-DT (10 May 70) 5th Ind

SUBJECT: Operational Report of HQ, 36th Signal Battalion (CA) for

Period Ending 30 April 1970, RCS CSFOR-65 (R2)

HQ, US Army, Pacific, APO San Francisco 96558

20 AUG 70

THRU: Commending Conerel, U. S. Army Strategie Communications Command, Port Husehues, Arisons 85631 Jolf Lept 75

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:


2LT, AGC

Asst AG

CF:

DA ACSFOR

CG USASTRATCOM-PAC



| DOCUMENT CONTROL DATA - R & D (Security classification of title, body of abstract and indexing sunntation must be entered when the overall report is classified. | | | |
|---|--|------------------------------------|------------------|
| 1. ORIGINATING ACTIVITY (Corporate author) | | 28. REPORT SECURITY CLASSIFICATION | |
| HQ, OACSFOR, DA, Washington, D.C. 20310 | | UNCLASSIFIED | |
| 1. REPORT TITLE | | <u></u> | |
| | | | |
| One wastered Barrett Lagrang Loomed NO. 26th Signal Battalian | | | |
| Operational Report - Lessons Learned, HQ, 36th Signal Battalion 4. DESCRIPTIVE NOTES (Type of report and inclusive dates) | | | |
| Experiences of unit engaged in counterinsurgency operations, 1 Feb to 30 Apr 70. 8. Author(8) (First name, middle initial, last name) | | | |
| S. AUTMOR(S) (First name, middle initial, last name) | | | |
| | | | |
| CO, 36th Signal Battalion | | | |
| 6. REPORT DATE 74. TOTAL NO. O | | PAGES | 7b. NO. OF REFS |
| 10 May 1970 | 13 | | |
| M. CONTRACT OR GRANT NO. | SA. ORIGINATOR'S | REPORT NUMB | (E N(3) |
| b. PROJECT NO. N/A | 702297 | | |
| 6. | 95. OTHER REPORT NO(3) (Any other numbers that may be essigned | | |
| • | this report) | | |
| 4 | | | |
| 10. DISTRIBUTION STATEMENT | | | |
| | | | |
| | | | |
| 11. SUPPLEMENTARY NOTES | 12. SPONSORING M | ILITARY ACTIV | ITY |
| N/A | OACSFOR, I | DA. Washin | gton, D.C. 20310 |
| |] | | |
| 13. ABSTRACT | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| 11 | | | |

DD . FORM .. 1473

UNCLASSIFIED
Security Classification